

AGM Transportation Report 12Sep2020

Ferry Terminal Approach

Recent concerns regarding lane markings and alignment when exiting the ferry terminal northbound (left) on Foster Point Rd have been forwarded to Ministry of Transportation and Infrastructure (MoTI). Residents and visitors are reminded to drive on the right side of the road to avoid oncoming traffic.

Moore Hill

Further repairs have been made to pavement on the south side of Moore Hill. Emcon completed pot hole repair earlier in the year and have followed up with spray patching this summer to help seal out water.

Permanent slope repair is not scheduled at this time but MoTI and Emcon will continue to monitor, and address safety concerns as they develop.

Feedback collected from Pilkey Point residents is that the repairs certainly help, and appear adequate in the short term.

Roadside Mowing

After somewhat of a delay, the mowing was completed by the end of June. Thanks to Joe and Emcon for ensuring the sub-contractor completed the job.

Gravel Roads

Feedback from MoTI regarding chip-sealing of remaining dirt roads on Thetis is that the Ministry's main priority is for maintenance of current road surfaces only. Emcon will continue proactively maintaining the road surfaces and conduct spot gravelling as needed, as well as responding to any issues reported by MoTI staff and island residents.

Emcon can be contacted 24/7 using their Road Reporting Line at [1 866 353-3136](tel:18663533136) or leave a voicemail at the yard for Joe [250 246-3431](tel:2502463431).

For all emergencies dial 911.

Stu Downey

Transportation Chair